

Order this document by EB257/D

# Motorola Semiconductor Engineering Bulletin

EB257

# **Detecting Loss of Clock on Modular Microcontrollers**

By Sharon Darley Austin, Texas

#### **General Information**

On modular microcontrollers, when the MODCLK pin is held low at the release of RESET and an external clock signal is applied to the EXTAL pin, the clock synthesizer is bypassed. Also, the bits in the synthesizer control register (SYNCR) have no effect on the operation of the clock.

Thus, a loss of clock cannot be detected when an external oscillator is used. This means that the external oscillator can be stopped and later restarted.

When MODCLK is held high at the release of RESET and the voltagecontrolled oscillator (VCO) generates the system clock signal, the clock logic can detect a reference failure, or loss of clock.

In this case, the limp status bit (SLIMP) in the SYNCR is set when a reference failure is detected. The state of the reset enable (RSTEN) bit in the SYNCR determines clock synthesizer operation.

If RSTEN is cleared, then the clock synthesizer will operate in a special mode called limp mode. Limp mode frequency may vary, depending on the device. Maximum limp mode frequency will not exceed half of the maximum system clock when the frequency control bit X in the SYNCR is 0 or maximum system clock frequency when X = 1. If RSTEN is set, then a loss of clock will cause a reset.





### Freescale Semiconductor, Inc.

## **Engineering Bulletin**

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and

#### How to reach us:

USA/EUROPE/Locations Not Listed: Motorola Literature Distribution, P.O. Box 5405, Denver, Colorado 80217, 1-800-441-2447 or 1-303-675-2140. Customer Focus Center, 1-800-521-6274

JAPAN: Motorola Japan Ltd.: SPD, Strategic Planning Office, 141, 4-32-1 Nishi-Gotanda, Shinagawa-ku, Tokyo, Japan, 03-5487-8488 ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd., Silicon Harbour Centre, 2 Dai King Street, Tai Po Industrial Estate,

Tai Po, New Territories, Hong Kong, 852-26629298

Mfax™, Motorola Fax Back System: RMFAX0@email.sps.mot.com; http://sps.motorola.com/mfax/;

TOUCHTONE, 1-602-244-6609; US and Canada ONLY, 1-800-774-1848

HOME PAGE: http://motorola.com/sps/

MOTOROLA

Mfax is a trademark of Motorola, Inc.

© Motorola, Inc., 1999

