



68848 CAMEL A (0E76N) ERRATA

(October 6, 1994)

The CAMEL rev A mask 0E76N conforms with the full specification of the 68848, with the following exceptions.

1. Asynchronous Interface and Clear-on Read Registers

When using the asynchronous interface, it is possible that reading events in Clear on Read registers may result in the event being cleared before the event is read out of the ELM. This errata applies to all clear-on-read registers, including the interrupt event register. In the case of the interrupt event register, this may cause failure of the PCM software, preventing the node from entering the ring.

Workaround:

- Poll the other status registers to assure no events are missed. This will allow the node to enter the ring successfully.

Notice

Specifications and information herein are subject to change without notice. Motorola reserves the right to make changes to any products described herein to improve functioning or design. Although the information in this document has been carefully reviewed and is believed to be reliable, Motorola does not assume any liability arising out of the application or use of any product, program, or circuit described herein; neither does it convey any license under its patent right nor the rights of others.

Motorola Inc.'s general policy does not recommend the use of its components in life support applications wherein a failure or malfunction of the component may directly threaten life or injury. Per Motorola Terms and Conditions of Sale, the user of Motorola components in life support applications assumes all risk of such use and indemnifies Motorola against all damages.