

# *Datapath Switch*

## *Errata to* **XC92501 ATM Cell Processor**

This document describes errata of the XC92501 ATM Cell Processor and its related versions:

- XC92501GC, August, 1998
- XC92501GCA, Rev. A, September, 1999

### **1.1 Summary Table**

Table 1-1 provides a summary of XC92501 errata.

**Table 1-1 Summary of XC92501 Errata**

Errata #	Problem	Impact	Work Around	Silicon Revisions Affected	
				GC	GCA
1	The MDC bit of the MPCRNR register cannot be read.	The MDC bit cannot be read.	MPCRNR(MDC) can be written and the XC92501 cell processor will function according to the specification.	✓	✓

This document contains information on a new product under development by Motorola. Motorola reserves the right to change or discontinue this product without notice.  
© Motorola, Inc., 1999. All rights reserved.



**MOTOROLA**

**For More Information On This Product,  
Go to: [www.freescale.com](http://www.freescale.com)**

Table 1-1 Summary of XC92501 Errata

Errata #	Problem	Impact	Work Around	Silicon Revisions Affected	
				GC	GCA
2	The per-connection and per-link ingress billing counters do not count when egress UPC is set.	Cells are not counted at ingress.	None	✓	✓
3	An ingress cell is removed during egress UPC.	Cells are lost at ingress.	None	✓	✓
4	The JTAG boundary scan register bit definition is updated.	The backward compatibility of the 92501 to the 92500 is marginally reduced.	None	✓	✓
5	I/O pins are not 5V tolerant		As a workaround Motorola recommends using buffers which are 5V tolerant and whose output is 3V for driving the RXPHYID(0->3) signals.	✓	

## 1.2 Errata Details

Following are the details of the errata that apply to the XC92501 ATM Cell Processor:

---

### **Errata #1: The MPCRNR(MPC) bit cannot be read**

---

<b>Description:</b>	Even when a new value has been placed in the MDC bit of the MPCRNR register it cannot be read.
<b>Projected Impact:</b>	The MDC bit cannot be read.
<b>Solution:</b>	A fix is planned for the XC92501.
<b>Work Around:</b>	The MPCRNR(MDC) bit can be written, however, and the XC92501 cell processor will function according to the specification.
<b>Errata Applies To:</b>	XC92501GC, XC92501GCA

---

**Errata #2: Billing counters do not count**

---

<b>Description:</b>	When the egress UPC is set, the per-connection and per-link ingress billing counters do not count.
<b>Projected Impact:</b>	Cells are not counted at ingress.
<b>Solution:</b>	A fix is planned for the XC92501.
<b>Work Around:</b>	None
<b>Errata Applies To:</b>	XC92501GC, XC92501GCA

---

**Errata #3: Removal of an ingress cell during egress UPC**

---

<b>Description:</b>	In egress UPC mode, when an egress cell is removed because it does not conform to UPC, one cell slot later an ingress cell is removed.
<b>Projected Impact:</b>	Cells are lost from the ingress cell flow.
<b>Solution:</b>	The XC92501 will be fixed in the next revision.
<b>Work Around:</b>	None
<b>Errata Applies To:</b>	XC92501GC, XC92501GCA

---

**Errata #4: JTAG boundary scan register bit definition is updated**

---

<b>Description:</b>	Because the XC92501 contains some additional signals that the MC92500 does not have, the JTAG boundary scan register bit definition of the XC92501 is updated, is changed from the MC92500.
<b>Projected Impact:</b>	The backward compatibility of the 92501 to the 92500 is marginally reduced.
<b>Solution:</b>	A fix is planned for the XC92501.
<b>Work Around:</b>	None
<b>Errata Applies To:</b>	XC92501GC, XC92501GCA

## Errata #5: I/O pins are not 5V tolerant

<b>Description:</b>	The RXPHYID(0->3) pins of the 92501 are not 5V tolerant.
<b>Projected Impact:</b>	
<b>Solution:</b>	This errata will be fixed in the next version of the processor.
<b>Work Around:</b>	As a workaround Motorola recommends using buffers which are 5V tolerant and whose output is 3V for driving the RXPHYID(0->3) signals.
<b>Errata Applies To:</b>	XC92501GC,

## 1.3 Revision History

Table 1-2 contains a brief description of the technical updates made to this document.

**Table 1-2Revision History Table**

Date	Document Revision	Substantive Changes
14 October, 1999	Rev 1.1	Errata 1, 2, and 4: Changed "No fix is planned for the MC92501" to "A fix is planned for the MC92501."
15 December, 1999	Rev 1.2	Changed all occurrences of MC92501 to XC92501 to reflect the true name of the silicon. Added the word "Silicon" to "Revisions Affected" in Table 1.



Mfax is a trademark of Motorola, Inc.

The PowerPC name, the PowerPC logotype, and PowerPC 603e are trademarks of International Business Machines Corporation used by Motorola under license from International Business Machines Corporation.

Information in this document is provided solely to enable system and software implementers to use PowerPC microprocessors. There are no express or implied copyright licenses granted hereunder to design or fabricate PowerPC integrated circuits or integrated circuits based on the information in this document.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part.

Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

#### Motorola Literature Distribution Centers:

**USA/EUROPE:** Motorola Literature Distribution; P.O. Box 5405; Denver, Colorado 80217; Tel.: 1-800-441-2447 or 1-303-675-2140;

World Wide Web Address: <http://ldc.nmd.com/>

**JAPAN:** Nippon Motorola Ltd SPD, Strategic Planning Office 4-32-1, Nishi-Gotanda Shinagawa-ku, Tokyo 141, Japan Tel.: 81-3-5487-8488

**ASIA/PACIFIC:** Motorola Semiconductors H.K. Ltd Silicon Harbour Centre 2, Dai King Street Tai Po Industrial Estate Tai Po, New Territories, Hong Kong

**Mfax™:** [RMFAX0@email.sps.mot.com](mailto:RMFAX0@email.sps.mot.com); TOUCHTONE 1-602-244-6609; US & Canada ONLY (800) 774-1848;

**World Wide Web Address:** <http://sps.motorola.com/mfax>

**INTERNET:** <http://motorola.com/sps>

**Technical Information:** Motorola Inc. SPS Customer Support Center 1-800-521-6274; electronic mail address: [crc@wmkmail.sps.mot.com](mailto:crc@wmkmail.sps.mot.com).

**Document Comments:** FAX (512) 895-2638, Attn: RISC Applications Engineering.

**World Wide Web Addresses:** <http://www.motorola.com/PowerPC>  
<http://www.motorola.com/netcomm>  
<http://www.motorola.com/Coldfire>



**MOTOROLA**

XC92501

**For More Information On This Product,  
Go to: [www.freescale.com](http://www.freescale.com)**