### NXP BSP LPC8N04 Release Notes

### BSP LPC8N04 version release history and known issues

The version history and known issue lists on this page are for v1.xx releases of BSP only.

Some issues are known at the time of the versioned package release.



# BSP v1.2 release (Released: 01/28/2019): NXP LPC8N04 Development Board support

#### **Features Added**

1) Added peripheral examples

#### **Changes and Fixes**

- 1) RTC Keil Release : change debugger from "ULINK" to "CMSIS-DAP"
- 2) Energy Harvest: change output binary name from "pmu" to "energy\_harvest" Known issues

#### **Known Issues**

None

# BSP v1.10 release (Released: 01/15/2018): NXP LPC8N04 Development Board support

#### **Features Added**

None

#### **Changes and Fixes**

• Cleaned up driver files

#### **Known issues**

None

BSP v1.00 release (Released: 12/05/2017): NXP LPC8N04 Development Board support

#### **Features Added**

None

#### **Changes and Fixes**

None

#### **Known issues**

None

#### How to Reach Us

Home Page: www.nxp.com

Web Support: www.nxp.com/support

#### **USA/Europe or Locations Not Listed:**

NXP Semiconductor

Technical Information Center, EL516

2100 East Elliot Road

Tempe, Arizona 85284

+1-800-521-6274 or +1-480-768-2130

www.nxp.com/support

#### Europe, Middle East, and Africa:

NXPHalbleiter Deutschland GmbH

**Technical Information Center** 

Schatzbogen 7

81829 Muenchen, Germany

+44 1296 380 456 (English)

+46 8 52200080 (English)

+49 89 92103 559 (German)

+33 1 69 35 48 48 (French)

www.nxp.com/support

#### Japan:

NXP Semiconductor

ARCO Tower 15F

1-8-1, Shimo-Meguro, Meguro-ku,

Tokyo 153-0064, Japan

0120 191014 or +81 3 5437 9125

support.japan@nxp.com

#### Asia/Pacific:

NXP Semiconductor Hong Kong Ltd.

**Technical Information Center** 

2 Dai King Street

Tai Po Industrial Estate

Tai Po, N.T., Hong Kong

+800 2666 8080

support.asia@nxp.com