




0000-000-40891 SOLDERPASTE\_1 COMP SIDE 2A0




0000-000-40891

SILKSCREEN\_1


COMP

SIDE

2A000




0000-000-40891 SOLDERMASK\_1 COMP SIDE 2A00



0000-000-40891

SIGNAL\_1


COMP SIDE 2A1



0000-000-40891

SIGNAL\_2

SOLDER SIDE 2A2




0000-000-40891

SOLDERMASK\_2


SOLDER

SIDE

2B00



0000-000-40891      SILKSCREEN\_2    SOLDER    SIDE    2B000



0000-000-40891


SOLDERPASTE\_2

SOLDER

SIDE

2B0





0000-000-40891  
DRILL DRAWING

DRILL CHART: TOP to BOTTOM			
ALL UNITS ARE IN MILLIMETERS			
FIGURE	SIZE	PLATED	QTY
E	0.2000	PLATED	21
G	0.3000	PLATED	42
J	0.4000	PLATED	12
L	0.5000	PLATED	4
⊙	0.7000	PLATED	4
Ⓢ	0.8000	PLATED	22
Ⓤ	0.9000	PLATED	2
Ⓐ	1.0000	PLATED	17
Ⓟ	0.6500	NON-PLATED	1
Ⓛ	1.1000x0.5000	PLATED	4
Ⓟ	0.9500x0.6500	NON-PLATED	1

TOTAL HOLES: 130

