

# **TEST REPORT**

APPLICANT : Amkor Technology Korea, Inc.

ADDRESS: 150, Songdomirae-ro, Yeonsu-gu,

Incheon, Korea

PAGE: 1 of 3

DATE: Jan. 06, 2025

REPORT NO. RT24R-S8364-007-E2

SAMPLE DESCRIPTION : The following submitted sample(s) said to be:-

NAME/TYPE OF PRODUCT : Bumping - Plated layer (SnAg)

SAMPLE ID NO. : RT24R-S8364-007 ITEM NO. : Sputter + SnAg

MANUFACTURER/VENDOR : Amkor Technology Korea, Inc.

SAMPLE RECEIVED : Dec. 10, 2024

TESTING DATE : Dec. 24, 2024 ~ Jan. 06, 2025

TEST METHOD(S) : Please see the following page(s).
TEST RESULT(S) : Please see the following page(s).

Approved by,

Authorized by,

四系3.

Jade Jang / Lab. Technical Manager

Bo Park / Lab. General Manager

Intertek Testing Services Korea Ltd.

Office: Tel: 031-8069-3708 Fax: 02-3409-0025 Web Site: intertek.co.kr Seoul Lab. Address: 7, Achasan-ro 5-gil, Seongdong-gu, Seoul, 04793 Korea







 $<sup>\</sup>ensuremath{^*}$  Note 1 : The test results presented in this report refer only to the object tested.

<sup>\*</sup> Note 2: This report shall not be reproduced except in full without the written approval of the testing laboratory.

<sup>\*</sup> Note 3 : The item no. is assigned by client and indicated according to their requirement and guarantee letter.



## **TEST REPORT**

PAGE: 2 of 3

REPORT NO. RT24R-S8364-007-E2 DATE: Jan. 06, 2025

SAMPLE ID NO. : RT24R-S8364-007

SAMPLE DESCRIPTION: Bumping - Plated layer (SnAg)

TEST ITEM	CAS NO.	UNIT	TEST METHOD	MDL	RESULT
Dibutyl phthalate (DBP)	84-74-2	mg/kg	With reference to IEC 62321-8 Edition 1.0 : 2017, by solvent extraction and determined by GC/MS	50	N.D.
Di(2-ethylhexyl) phthalate (DEHP)	117-81-7	mg/kg		50	N.D.
Benzyl butyl phthalate (BBP)	85-68-7	mg/kg		50	N.D.
Diisobutyl phthalate (DIBP)	84-69-5	mg/kg		50	N.D.


Tested by : Hayan Park

Notes: mg/kg = ppm = parts per million

< = Less than

N.D. = Not detected ( <MDL )
MDL = Method detection limit

<sup>\*</sup> View of sample as received;-



Intertek Testing Services Korea Ltd.

Office: Tel: 031-8069-3708 Fax: 02-3409-0025 Web Site: intertek.co.kr Seoul Lab. Address: 7, Achasan-ro 5-gil, Seongdong-gu, Seoul, 04793 Korea







## **TEST REPORT**


PAGE: 3 of 3

REPORT NO. RT24R-S8364-007-E2

DATE: Jan. 06, 2025

SAMPLE ID NO. : RT24R-S8364-007

SAMPLE DESCRIPTION: Bumping - Plated layer (SnAg)



#### \*\*\*\*\* End of Report \*\*\*\*\*

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: http://www.intertek.com/terms/. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.

This report shall not be reproduced, except in full.

This report is not related to the scope of Korea Laboratory Accreditation Scheme.

#### Intertek Testing Services Korea Ltd.

Office: Tel: 031-8069-3708 Fax: 02-3409-0025 Web Site: intertek.co.kr Seoul Lab. Address: 7, Achasan-ro 5-gil, Seongdong-gu, Seoul, 04793 Korea



